

MONSOON ACTION PLAN

DIVISION-27,
North Zone, GHMC
2017-18

INDEX

Sl.No	Particular	Pg.no
1	Names and contact numbers of higher authorities department wise	
2	Details of staff working in 133-Macha Bollarum	
3	Details of staff working in 134-Alwal	
4	Details of staff working in 135-Venkatapuram	
5	Tools available in ward offices	
6	Major and critical water logging places in Hyderabad traffic police limits for the year 201	
7	Minor water logging places in Hyderabad traffic police limits for the year	
8	Proposals for monsoon preparedness plan for the year 2017-18	

Names and contact numbers of higher authorities department wise

Sl. No	Department	Name of the officer	Designation	Contact number
1	GHMC	Sri. ED Vijaya Raju	Zonal Commissioner, North Zone	
2	GHMC	Smt. Nalini Padmavathi	Dy. Commissioner, Alwal Circle	9177701938
3	GHMC	Sri. A.Ashwin Kumar	Superintending Engineer, North Zone	9849006023
4	GHMC	Sri.P.Anil Raj	Executive Engineer, Alwal Circle	9989930374
5	GHMC	Smt.K.Helen Nirmala	AMOH	9701363243
6	GHMC	Sri. S.Raja Sekhar	ACP	9989930419
7	GHMC	Sri.N.Rajendra Kumar	Dy. Director Horticulture	8978031168
8	GHMC	Sri.P.Kamalakar Reddy	Manager, Horticulture	7995079816
9	GHMC	Smt.V.Rathna Rani	Dy.Project Officer	9849028569
10	HMWS&SB	Sri.Sreedhar Reddy	General Manager	9989994110
11	HMWS&SB	Sri.Ravi Kumar	General Manager	9989995779
12	Traffic	Sri.K.Ramulu	CI	9490617243
13	Traffic	Sri.G.V Shyam Sunder Reddy	ACP	8332981179
14	Law & Order	Sri.T.Anand Reddy	CI	9490617215
15	Law & Order	Sri.A.Srinivasa Rao	ACP	9490617467
16	Fire	Sri.G.Venkatেশ war	Station fire Officer	9393936168
17	Street Light	Sri.V.Joseph	Executive Electrical	9100025160
18	TSPDCL	Sri.N.Sridhar	ADE	9440812847
19	TSPDCL	Sri.S.Laxman	AE	9440812904
20	Revenue	P.Padma Priya	MRO	7995073761

MACHA BOLLARUM DIVISION

I)ENGINEERING:

Sl.No	Designation	Name of the officer	Contact number
1	Superintending Engineer	Sri. A.Ashwin Kumar	9849006023
2	Executive Engineer,	Sri.P.Anil Raj	9989930374
3	Dy.Executive Engineer	E.Prasad Rao	7995079772
4	Asst. Engineer	Ch. Vijayender Reddy	7995079758
5	Work Inspector	M.Bhadraiah	9177927134

II)HMWS&SB:

Sl.No	Designation	Name of the officer	Contact number
1	GM (O&M)	Sri.Sreedhar Reddy	9989994110
2	GM (Projects)	Sri.Ravi Kumar	9989995779
3	DGM	Smt.Rajini.C	9989995278
4	Manager	Sri.Chandraprakash	

III)Traffic:

Sl.No	Designation	Name of the officer	Contact number
1	ACP	Sri.G.V Shyam Sunder Reddy	8332981179
2	CI	Sri.K.Ramulu	9490617243

IV)Law & Order Police:

Sl.No	Designation	Name of the officer	Contact number
1	CI	Sri.T.Anand Reddy	9490617215
2	SI	N.Ramulu	8332981127

V)Fire Department:

Sl.No	Designation	Name of the officer	Contact number
1	Station Fire Officer	G.Venkateshwar	9393936168
2	Land line		040-23449227

VI)Revenue Department:

Sl.No	Designation	Name of the officer	Contact number
1	MRO	P.Padma Priya	7995073761

VII)UBD:

Sl.No	Designation	Name of the officer	Contact number
1	Dy. Director Horticulture	Sri.N.Rajendra Kumar	8978031168
2	Manager, Horticulture	Sri.P.Kamalakar Reddy	7995079816

VIII)Medical Department:

Sl.No	Designation	Name of the officer	Contact number
1	Health Officer	Smt.K.Helen Nirmala	9701363243
2	Sanitary Supervisor	Sri.K.Jalandhar Reddy	8970522488

IX)Town planning Section:

Sl.No	Designation	Name of the officer	Contact number
1	ACP	Sri.S.Rajsekhar	9989930419
2	Section office	Sri.E.Ashok Kumar	9100025138

X)UCD:

Sl.No	Designation	Name of the officer	Contact number
1	DPO	Smt.V.Rathna Rani	9849028569
2	CO	Sri.G.Jagadishwar Goud	9177666456

XI)Entomology:

Sl.No	Designation	Name of the officer	Contact number
1	Asst. Entomologist	Sri.T.Thirupathi Raju	9959552464

XII)TSPDCL:

Sl.No	Designation	Name of the officer	Contact number
1	ADE	Sri.N.Sridhar	9440812847
2	AE	Sri.Rajinikanth	9440812906

ALWAL DIVISION

I)ENGINEERING:

Sl.No	Designation	Name of the officer	Contact number
1	Superintending Engineer	Sri. A.Ashwin Kumar	9849006023
2	Executive Engineer,	Sri.P.Anil Raj	9989930374
3	Dy.Executive Engineer	Sri. B.Maheshwar	9959226998
4	Asst. Executive Engineer	Sri.Virat Raj Kumar	8008071177
5	Work Inspector	Sri.A.Srikanth	9618130790
6	Work Inspector	Sri.J. Chandu	7416510645

II)HMWS&SB:

Sl.No	Designation	Name of the officer	Contact number
1	GM (O&M)	Sri.Sreedhar Reddy	9989994110
2	GM (Projects)	Sri.Ravi Kumar	9989995779
3	DGM	Smt.Rajini.C	9989995278
4	Manager	Sri.Chandraprakash	

III)Traffic:

Sl.No	Designation	Name of the officer	Contact number
1	ACP	Sri.G.V Shyam Sunder Reddy	8332981179
2	CI	Sri.K.Ramulu	9490617243

IV)Law & Order Police:

Sl.No	Designation	Name of the officer	Contact number
1	CI	Sri.T.Anand Reddy	9490617215
2	SI	Sri. D.Madhusudhan Reddy	8332982116

V)Fire Department:

Sl.No	Designation	Name of the officer	Contact number
1	Station Fire Officer	G.Venkateshwar	9393936168
2	Land line		040-23449227

VI)Revenue Department:

Sl.No	Designation	Name of the officer	Contact
--------------	--------------------	----------------------------	----------------

o			number
1	MRO	P.Padma Priya	7995073761

VII)UBD:

Sl.N o	Designation	Name of the officer	Contact number
1	Dy. Director Horticulture	Sri.N.Rajendra Kumar	8978031168
2	Manager, Horticulture	Sri.P.Kamalakar Reddy	7995079816

VIII)Medical Department:

Sl.N o	Designation	Name of the officer	Contact number
1	Health Officer	Smt.K.Helen Nirmala	9701363243
2	Sanitary Supervisor	Sri.K.Jalandhar Reddy	8970522488

IX)Town planning Section:

Sl.N o	Designation	Name of the officer	Contact number
1	ACP	Sri.S.Rajsekhar	9989930419
2	Section office	Smt.B.Sridevi	7995020416

X)UCD:

Sl.N o	Designation	Name of the officer	Contact number
1	DPO	Smt.V.Rathna Rani	9849028569
2	CO	Smt.Kavitha	

XI)Entomology:

Sl.N o	Designation	Name of the officer	Contact number
1	Asst. Entomologist	Sri.T.Thirupathi Raju	9959552464

XII)TSPDCL:

Sl.N o	Designation	Name of the officer	Contact number
1	ADE	Sri.N.Sridhar	9440812847
2	AE	Sri.Sudhakar	9440812904

VENKATAPURAM DIVISION

I)ENGINEERING:

Sl.No	Designation	Name of the officer	Contact number
1	Superintending Engineer	Sri. A.Ashwin Kumar	9849006023
2	Executive Engineer,	Sri.P.Anil Raj	9989930374
3	Dy.Executive Engineer	Sri. B.Maheshwar	9959226998
4	Asst. Executive Engineer	Sri. B.Bhanu Chander	8790522433
5	Work Inspector	Sri. E.Vijaya Rama Rao	9989979949
6	Work Inspector	Sri.A.K Venkat Rao	9394117885

II)HMWS&SB:

Sl.No	Designation	Name of the officer	Contact number
1	GM (O&M)	Sri.Sreedhar Reddy	9989994110
2	GM (Projects)	Sri.Ravi Kumar	9989995779
3	DGM	Smt.Rajini.C	9989995278
4	Manager	Sri.Chandraprakash	

III)Traffic:

Sl.No	Designation	Name of the officer	Contact number
1	ACP	Sri.G.V Shyam Sunder Reddy	8332981179
2	CI	Sri.K.Ramulu	9490617243

IV)Law & Order Police:

Sl.No	Designation	Name of the officer	Contact number
1	CI	Sri.T.Anand Reddy	9490617215
2	SI	Sri. N.Laxminarayana	9177697428

V)Fire Department:

Sl.No	Designation	Name of the officer	Contact number
1	Station Fire Officer	G.Venkateshwar	9393936168
2	Land line		040-23449227

VI)Revenue Department:

Sl.No	Designation	Name of the officer	Contact number
1	MRO	P.Padma Priya	7995073761

VII)UBD:

Sl.No	Designation	Name of the officer	Contact number
1	Dy. Director Horticulture	Sri.N.Rajendra Kumar	8978031168
2	Manager, Horticulture	Sri.P.Kamalakar Reddy	7995079816

VIII)Medical Department:

Sl.No	Designation	Name of the officer	Contact number
1	Health Officer	Smt.K.Helen Nirmala	9701363243
2	Sanitary Supervisor	Sri.K.Jalandhar Reddy	8970522488

IX)Town planning Section:

Sl.No	Designation	Name of the officer	Contact number
1	ACP	Sri.S.Rajsekhar	9989930419
2	Section office	Sri.P.Ashok Raj	7794076738

X)UCD:

Sl.No	Designation	Name of the officer	Contact number
1	DPO	Smt.V.Rathna Rani	9849028569
2	CO	Sri.A.Balraj	

XI)Entomology:

Sl.No	Designation	Name of the officer	Contact number
1	Asst. Entomologist	Sri.T.Thirupathi Raju	9959552464

XII)TSPDCL:

Sl.No	Designation	Name of the officer	Contact number
1	ADE	Sri.N.Sridhar	9440812847
2	AE	Sri.Sudhakar	9440812904

Tools Available in Alwal Circle, NZ, GHMC

1. Generator	-	01
2. Mud Motor	-	01
3. Gas Cutter	-	01
4. Electric pump	-	01
5. Crowbars	-	03
6. Axe	-	04
7. Rope	-	01
8. Gamalas	-	05
9. Drilling machine	-	01
10. Aluminium Ladder	-	01
11. LCD Dragon Light	-	01
12. Safety Helmets	-	23
13. Rain Coats	-	10
14. Radium Jackets	-	12
15. Radium cones	-	17
16. Gum Shoes	-	44
17. Cable Cutter	-	02
18. Mega Phone	-	02
19. Radium Chain	-	01
20. Gun/ Sledge Hammer	-	02
21. Spades	-	02
22. Small Cylinder	-	01
23. Small Torch Lights	-	10
24. CFL Lamps	-	02

Tools Available at TSPSDCL

1. Utility Vehicle	-	01
2. Safety Belts	-	06
3. Helmets	-	06
4. Rain Coats	-	06
5. Earth Rods	-	06
6. Hand Gloves	-	06
7. Gum Boots	-	06
8. Linemen Kit	-	01

CRITICAL ISSUES IDENTIFIED IN CIRCLE -16, GHMC.

Sl.No	Ward No	Location	Reasons for Problem / Critical Issues	Action Proposal (mid term plans)	Remarks	
					Short term plans	Long term plans
1	133	Drainage out let problem at Turkapally	The huge quantity of flood water from Hakimpet air port passes in to Turkapally village and ARK Homes. Due to this areas are submerged with flood water.	Recently desilted the SW drains which has fully filled with silt and gobar.	Desilting and clearing of jungle clearance across the railway track by taking permission from railway authorities for free flowing of drainage and flood water	Proposed to construction of SW drain from Turkapally village (via Gummadi Krishnareddy Colony) to Buttonguda culvert
2	133	Water stagnation from Mothukulakunta cheruvu to Jyothi nagar near select talkies	The flood water from mothukulakunta cheruvu will inundate colonies like venkateshwara colony, jyothinagar, chandranagar. It is very important to repair the existing nala and regulate the width of the nala by removing encroachments like compound walls etc so that water may pass into kotha cheruvu easily.	It is very important to repair the existing nala and regulate the width of the nala by removing encroachments like compound walls etc so that water may pass into kotha cheruvu easily	The monsoon emergency team will clear stagnation time to time	
3	133	Repairs to retaining wall and fencing to the nala at Kotha basthi and other places in W.no.133	The nala from Prem nagar colony to Kotha basthi is to be protected by fencing.. It is very essential to repairing the nala and to provide fencing.	It is very important to take up the work of repairing nala and providing fencing at Kothabasthi to railway tunnel before monsoon.	The monsoon emergency team will monitor at the time of rain fall	
4	133	Culverts at Maa SanthoShi Colony, Risala Bazar	The existing culverts on nala at Maa santho shi colony, risalabazar are completely damaged as the culverts are constructed 20 years back and unable to coup up. It is very essential to construct new culvert in place of damaged culvert.	It is very essential to construct new culvert in place of damaged culverts t Maa santhoshi Colony and Risala Bazar.	The monsoon emergency team will monitor at the time of rain fall	

5	134	Water stagnation at Sree Bakery, Reddy Enclave & Bharathi Nagar and Anadrao nagar of Old Alwal	The huge quantity of flood water from kotha cheruvu passes in to chinarayuni cheruvu through open nala via residential colonies. Reddy Enclave at sree bakery, Bharathi Nagar and Anandrao Nagar are tail end colonies and are near FTL of chinarayuni cheruvu. During floods huge quantity of water flows on the roads of Reddy Enclave and Bharathi nagar . At present the level of last road near chinaryuni cheruvu and level in the chinaryuni chervu will be same at the time of floods. This problem can be solved by widening the nala and very importantly fixing and clearing FTL of Chinarayuni cheruvu so that water will easily pass into water body.	Recently this office has taken up remodeling of existing nala on either sides of the road and road crossing culvert which is blocked since years. The remodeling comprising of silt clearance, raising of retaining walls and slab. In addition to that no.of cables which were crossing the nala were lifted out and placed aside.	The monsoon emergency team will clear stagnation time to time	The existing nala has to be widened as per norms. Recently the Town planning wing and lakes division has conducted survey for widening of nala.
6	134	Water stagnation at Lothukunta main road and Maruthi Nagar road	It is a Highway road leads to Karimnagar and experiences heavy traffic. During rain fall a heavy stagnation occurs below the ROB and there is no out let to drive out. Secondly there is a sub road beside ROB which leads to maruthi nagar is also experiences a heavy stagnation by receiving flood water from defence area and will stay on the road until evacuation. Both the stagnations disturbs the commuters. It is very essential to lay storm water drain from maruthi nagar point to existing open storm water drain at Shobha sri Garden function hall via ROB on Lothukunta main road so that flood water may drive out.	It is essential to lay storm water drain from maruthinagar road to Shobha sri Garden function hall via ROB on Lothukunta main road to drive out the flood water.	The monsoon emergency team will clear stagnation time to time	--

7	134	Water stagnation at Laxmikalamandir	It is a age old damaged open storm water drain which carries flood water and drainage water of around 10 colonies to existing open nala beside railway track. The present condition of this drain is that the drain is completely damaged and the water is over flowing on the roads. It is very essential to remodel the storm water drain by widening the section with proper levels.	It is very essential to remodel the storm water drain by widening the section with proper levels, so that flood water may easily pass into nala beside railway track.	The monsoon emergency team will clear stagnation time to time	--
8	134	Damaged culvert in Bharathi Nagar	The huge quantity of flood water from kotha cheruvu passes in to chinarayuni cheruvu through open nala via residential colonies. Reddy Enclave at sree bakery, Bharathi Nagar and Anandrao Nagar are tail end colonies and are near FTL of chinarayuni cheruvu. During floods huge quantity of water flows on the roads of Reddy Enclave and Bharathi nagar . There is a half length culvert constructed on the nala and leaving remaining length open to sky. During last year floods, the water stagnate on the roads of barathi nagar colony at a level of 2' to 3' height and the above said culvert was completely submerged. There was a danger that commuters may fall into the nala at Half culvert open portion. This office has engaged monsoon emergency team at the site and constructed walls to the open portion and prevented accidents. It is very essential to construct culvert .	It is very essential to construct culvert.	The monsoon emergency team will monitor this point at the time of rain fall	
9	134	Repairs to retaining wall and fencing to the nala in Harijan basthi	The nala from Kotha cheruvu to chinarayuni cheruvu is being protected by fencing. The existing retain wall and fencing has been damaged and washed out during last year heavy floods in harijan basthi and other few stretches. It is very essential to repairing the nala and providing fencing.	It is very important to take upthe work of repairing nala and providing fencing at harijan basthi and other places before monsoon.	The monsoon emergency team will monitor at the time of rain fall	

10	134	Harijan Basthi	<p>The huge quantity of flood water from kotha cheruvu passes in to chinarayuni cheruvu through open nala via residential colonies. Reddy Enclave at sree bakery, Bharathi Nagar and Anandrao Nagar are tail end colonies and are near FTL of chinarayuni cheruvu. During floods huge quantity of water flows on the roads of Reddy Enclave and Bharathi nagar . The open nala oneither sides of the road is concealed by RCC pre cast slabs around 10 years back. Most of the slabs are damaged and it is very essential to provide pre cast slabs and to repair the existing SW drain wherever required</p>	<p>It is very essential to repair the existingdamaged SW drain and to provide RCC pre cast slabs wherever necessary to avoid accidents in rainy season.</p>	<p>The monsoon emergency team will monitor at the time of rain fall</p>
11	135	Water stagnation at Gollaguda Kaman, Subash nagar and Brundavan Colony	<p>The huge quantity of flood water from defence area pass into adjacent subashnagar colony and will pass into nala at shivanagar culvert by flowing on the roads of subashnagar gollaguda Kaman and Brundavan colony. The flood water will flow on the roads for 4 to 5 days at every spell of rain fall and create lot of inconveninace to the residents as well as commuters. There is no drainage for channeling the flood water from defence colony compound wall to shivanagar culvert. It is very very essential to lay storm water drain to conceal the flood water.</p>	<p>Flood water continuously flows on the roads for 4 to 5 days at the time of rainfall by creating lot of troubles to the commuters. It is very essential to lay storm water drain from cantonment compound wall to brundavan colony junction and to shiva nagar culvert.</p>	<p>The monsoon emergency team will monitor this point at the time of rain fall</p>
12	135	Damaged culvert at Rahul Enclave, Shivanagar	<p>It is a culvert on nala which is completely collapsed and is in a dangerous position. The people dumped debris in the nala to culvert height and using as thorough fare. During rain fall this nala and the culvert will submerge and water will flow above the ground level. It is very very important to construct culvert over nala unless there is a 100% chance for accidents.</p>	<p>It is very essential to construct culvert.</p>	<p>The monsoon emergency team will monitor this point at the time of rain fall</p>

13	135	Water stagnation at IG Statue in Indiranagar	It is a low lying point and the flood water accumulates at this point and the residents of Indiranagar, Rajivnagar etc will face lot of inconvenience as it is at the entrance of the colony	This office is laid storm water drain with a cost of Rs.2.60 Lakhs under water stagnation points sanctioned last year. This storm water drain will carry and clear the flood water by taking short time during rainfall.	The monsoon emergency team will clear stagnation time to time	
14	135	Water stagnation at Sai Nagar, Khanajiguda	It is a low lying point and junction where flood water is coming from 4 roads and mainly huge quantity is coming from Sathya Sai Enclave and Indiranagar etc . During stagnation the adjacent houses are effected and flood water enter into the houses	It is very essential to repair and extend the existing storm water drain.	The monsoon emergency team will clear stagnation time to time	
15	135	Repairs to retaining wall and fencing to the nala at Shivanagar, Khanajiguda and	The nala from chinarayuni cheruvu to Hasmathpet cheruvu is being protected by fencing. The existing retain wall and fencing has been damaged and washed out during last year heavy floods in shivanagar, khanajiguda and chinarayuni cheruvu area etc. It is very essential to repairing the nala and providing fencing.	It is very important to take up the work of repairing nala and providing fencing at shivanagar, khanajiguda and chinarayuni cheruvu area etc before monsoon.	The monsoon emergency team will monitor at the time of rain fall	
16	136	Nagirddy Kunta to Kapra cheruvu via Shaili Garden, SS Enclave	The flood water comes from Kowkooor and nagi reddy kunta will submerge colonies like Swarnadhra Colony, Shaili Garden and SS enclave near Kapra cheruvu. The submergens occurring due to encroachments on nala and difference in width of nala at few stretches . It is very important to repair the existing nala and regulate the width of the nala by removing encroachments like compound walls and ramps etc so that water may pass into kapra cheruv easily and thus clear the submergence.	It is very important to repair the existing nala and regulate the width of the nala by removing encroachments like compound walls and ramps etc.	The monsoon emergency team will clear stagnation time to time	

MONSOON PREPAREDNESS - Teams and Readiness

S.No	Ward	Name of the Work	Estimate Amount	Teams /Shifts	No. Of Labours	Status	Remarks
1	3	4	5	6	7	8	9
1	133,134, 135&136P	Engaging of DCM along with labour for MOBILE MONSOON EMERGENCY TEAM for the year 2017-18 to work in Alwal Circle	21.90	3	6		
2	133	Engaging of Auto trolley (TATA Acer) along with labour for MINI MOBILE MONSOON EMERGENCY TEAM for the year 2017-18 to work in Ward.no.133 of Alwal Circle	11.40	3	4		
3	134	Engaging of Auto trolley (TATA Acer) along with labour for MINI MOBILE MONSOON EMERGENCY TEAM for the year 2017-18 to work in Ward.no.134 of Alwal Circle	11.40	3	4		
4	135	Engaging of Auto trolley (TATA Acer) along with labour for MINI MOBILE MONSOON EMERGENCY TEAM for the year 2017-18 to work in Ward.no.135 of Alwal Circle	11.40	3	4		
5	136p	Engaging of Auto trolley (TATA Acer) along with labour for MINI MOBILE MONSOON EMERGENCY TEAM for the year 2017-18 to work in Ward.no.136 P of Alwal Circle	11.40	3	4		
6	133,134, 135&136P	Procurement of tools and equipment including diesel mud pumps as a part of monsoon preparedness for Alwal Circle, GHMC	8.60				
			81.10				

PROPOSALS SANCTIONED UNDER MONSOON VULNERABLE POINTS

Sl.No	Ward.no.	Name of the Work	Estimate Cost (Rs.in Lakhs)	Status	Remarks
1	134	Laying of 600mm dia RCC pipe storm water drain for removal of water stagnation from Maruthi Nagar road to existing storm water drain near Shobha Sri Garden Function hall via ROB on Lothukunta main road in Ward.no.134 of Alwal Circle	38.50		
2	134	Repairs to existing storm water drain from Laxmikalamandhir to Railway track in Ward.no.134	25.75		
3	134	Repairs to existing nala and providing fencing at Harijan basthi and other places in Ward.no.134	10.70		
4	134	Repairs to existing Sw drain and providing precast slabs from Kotha Cheruvu to Srinivas Nagar and other places in Ward.no.134 of Alwal Circle	10.30		
5	134	Construction of culvert in place of collapsed culvert over existing nala and repairs to existing nala in Barathi Nagar near Chinarayuni cheruvu of ward.no.134	5.30		
6	135	Laying of 600mm dia RCC pipe storm water drain for removal of water stagnation from Lord Krishna Temple to existing nala at Shivanagar culvert in Brundavan nagar colony in Ward.no.135, Alwal Circle	41.00		
7	135	Repairs to existing nala and providing fencing from Chinarayuni cheruvu to Khanajiguda main road via Shiva Nagar of Alwal Circle	19.00		
8	135	Laying of 450mm dia RCC pipe storm water drain for removal of water stagnation from cantonment compound wall to Brundavan Colony junction via Gollaguda kaman in Ward.no.134 & 135 of Alwal Circle	30.00		
9	135	Construction of culvert in place of collapsed culvert over existing nala in Shivanagar, Ward.no.135	9.50		